

# Step Change Safety Alert Template



## Alert Title

Controlled shutdown following reported smell of gas

*What leaked and where from? E.g.: "Lube oil leak from compressor system open vent"*

## Incident Date

05/07/2013

*The date on which the incident occurred, not when this form was completed*

## Location Type

Fixed Production

*E.g. Floating/Fixed Production, Drill Rig, Vessel, etc.*

## Specific Equipment Involved

6" Fuel gas line

*Give as much detail as possible about the equipment involved*

## Description of What Happened

Assailers working in CD 16 reported smelling gas which, on investigation, was identified as coming from below the insulation on a 6" fuel gas supply line

NO FIXED DETECTION WAS ACTIVATED however portable detection indicated 50% LEL at a distance of 10cm.

Area evacuated and a controlled shutdown initiated by platform operations staff

*Be as detailed as possible. Give equipment history and approximate time(s) of actions/occurrences related to the incident*

## Cause of Incident

Corrosion under insulation caused by water ingress into the insulation

*Build from OIR/12 checklist*

## Incident Consequences

Platform hydrocarbon production systems shutdown & made safe. Leaking line vented and isolated.

After removal of the insulation, corrosion was found at the release location.

The Identified hole was estimated at 0.5 mm, with the corrosion scab place, prior to cleaning. The hole that was found when the corroded area was cleaned measured 5 mm.

It is believed that the corrosion scab was effectively being held in compression against the hole by the insulation.

*Include the release itself and any subsequent emergency actions/dangerous occurrences*

## Lessons Learned

Other than the inspection strategy, which leaves up to a 7 year gap between inspections, there is no process in place to prevent/monitor and repair damage to lagging before corrosion occurs. Whilst the strategy is considered to be robust there is a lack of assurance activities surrounding it to prevent a repeat of the incident since there is no particular reference made to CUI (corrosion under insulation) in the performance standard.

*Include a few bullet points clarifying what was learned from the incident*

## Recommendations/Actions

Remove the remaining lagging on the 6" fuel gas line and inspect closely for any signs of corrosion

Inspect insulation local to the area for indications of CUI, damage, or deterioration.

Review the current inspection strategy for this and similar pipework within the standard inspection model.

Raise awareness of CUI and the consequences of damaged paintwork in the corrosion awareness programme

*Include a few bullet points stating any recommendations/actions that will be made/taken as a result of the lessons learned*

## Contact Details (Optional)

*If you would like your submission to be anonymous, leave this section blank*