

Safety Alert

Number: 25-04

Published: 12/03/2025

Subject: Spill During Bulk Transfer

What Happened / Narrative

During offshore operations the vessel was lined up to receive Offshore Contaminated Bulk Liquid (Slops) from the rig. When the transfer started the bridge crew noticed a spray / mist from the strainer on the port side.

An "All stop" was called and rig quickly stopped the transfer. Approximately 4 litres were estimated to have leaked onto the vessels deck through an open strainer vent cock and 1 litre is estimated to have been sprayed onto the sea.

Why Did it Happen / Cause

After recent strainer checks and maintenance the vent cock had not been closed. Pre-start checks for the bulk transfer did not capture the fact that the vent cock was open.

Corrective Actions Taken / Recommendations

A Time Out For Safety was held by both shifts.

The wet bulk transfer risk assessment, toolbox talk and checklist have been updated to include checks of the strainer vent cocks.

An experience transfer was raised to share findings with other vessels within the fleet.

Planned Maintenance System task updated to include confirming all valves are in the correct position on completion of maintenance.

Photographs / Supporting Information



The information contained within this Safety Alert and the associated MSF web site is provided in good faith for the benefit of our members and does not constitute and is not intended to constitute professional advice or any form of formal representation on behalf of any MSF member or officer. The text as provided by submitting organisations may be amended to ensure that it is brief, informative and readable but will as far as reasonably practicable remain as per the intent of the original submission. For the avoidance of doubt, no liability whatsoever shall be attached to any guidance, recommendation or statement contained therein. Contents should be reviewed individually by recipients who will determine relevance to their own operations.