



1
Holed high pressure (60psi)
lube oil pipe identified on
Turbine A

Apparent failure mechanism
inconsistent with fire
damage



3
Turbine B
equivalent
line