



Spanner fell through gap between Column & fixed platform, deflecting off ledge on top of brick coarse.

Bunted area whilst in place, was not large enough to encompass "drop zone"





Drop mats were in place, however did not run right to column wall, a blanket was in place at this point but was disturbed during task leaving penetration exposed.