## Repair Pre Inspection - Damp and Mould



**Employee:** Ted Pearson

Order Number: 8053053

Job Address:

Visit Date: 11/11/2025

125 Bliss Road
Dorchester
Dorset
DT1 1XJ

Inspection Result: Repair required

Planned Order Details			
Target Completion Date	19/01/2026		
Priority	Inspections		
Work Type	Yes		
Price Book	Inspection & Survey		
Message 1	Customer reports damp and mould in the bedroom – Unable to book for several weeks		
Message 2	Customer apparently reported to the carpenter during window repair in October		
Weather conditions	Wet Temperature 10		
Number of occupants 1 Number of rooms	5 Number of bedrooms 3		

Bedroom 1 (Double) heating				
Heating provision	Radiator	Can a heat source be installed		
Radiator TRV setting	0			
Radiator suitable output	Yes	Radiator suitable position	Yes	
Does the window have trickle vents	Yes			

A few extracts from the surveyor's report on key findings



Bedroom 1 (Double) measurements						
Is the customer reporting mould in this room (or repair needed)		Yes				
Air temperature	14		Humidity (RH)	25		
			Psychometric Dew	point	– Readings	
Air quality			20			
10 40 50 0 70 95 00 7		Hygrometer – hygrometer				
		bedroom window				
Trickle vents used	Open		Window condition	1	Fair	
Internal door conditio	n	Good	10mm gap under	door	for airflow	Yes

Bedroom 1 (Double) Ceiling						
Skelling ceilings	No		Ceiling finish	Skimmed and Painted		
Bedroom 1 (Double) N	Bedroom 1 (Double) Mould					
Mould present in the	room Yes			Mould types present		Black Spot Mould
Bedroom 1 (Double) Water ingress or leak						
Signs of water ingress or leak				No		
Bedroom 1 (Double) Temperature						
Datum point surface	ace wall temperature 22		22	Surface wall temperature		22
		readings				

Bedroom 1 (Double) Repairs			
Damage and cause Contributing factors	Damp and mould caused by cold room window broken letting in cold air - also single glazing does not keep heat in		
Repairs required	No		

HHRSR	Mould Risk Score
Damp & Mould Growth	Severe
Inspection Result	Repair required
Inspector Findings	Damp and mould found in the bedroom caused by room being too cold
Inspector Comments HHRSR Mould Risk Score	
Refer to Asset	No
Extra information needed	No
Internal referral	No
Legal	No
NCMW	No
No work	No
Outside referral	No
Repairs required - appt	No
Repairs required - Unappoint	Yes
Subcontract	No