



Narcotic Effects of Hydrocarbons

TEMPSC (Lifeboat) Diesel Fuel Quality

Updated: Elevator Guide Roller Drops to Deck Below

Crate Lid Dislodged Overboard During Heli Ops

Dropped Elevator Bumper Stop



Structural failure of rescue boat

High potential: spontaneous opening of hydraulic release shackle (HRS) pin

NTSB: diesel generator engine failure

LTI: fall from height during anchor chain handling operation

Sudden disconnection of pressurised hose



Effective Winterisation Strategies for Ensuring Process Safety



Vessels Gangway Fell from Quay