



Quarterly Themes


Q3

Jul Aug Sep



Safe Lifting, Working at Height and Preventing Dropped Objects

FEATURED RESOURCES



Lifting and Mechanical Handling Guidance

STEP CHANGE IN SAFETY TOOLBOX TALK FORM		PORTABLE REGIONAL OPERATIONS	
DELIVERY OF TALK TIPS:			
<ul style="list-style-type: none"> Keep a record and ensure you engage with the team Ask relevant and open questions to confirm understanding with team Keep a reference to this talk and discuss any observed Contact the TST at or near the workplace where conditions allow learning and understanding Thoroughly discuss any observed or potential hazards 			
WHEN Date / shift:	DOCUMENTATION AVAILABLE:	N/A	<input checked="" type="checkbox"/>
WHO Department:	Lift Plan / Risk Assessment	<input type="checkbox"/>	<input type="checkbox"/>
WHERE Location:	Permit to Work	<input type="checkbox"/>	<input type="checkbox"/>
Reference Number:	Lessons Learned	<input type="checkbox"/>	<input type="checkbox"/>
WHAT Explain the work			

Lifting and Mechanical Handling Guidance



Dropped Objects Pack



Crane Incident film and notes




Lifting Operations Pack



Safety Moment – Prevention of Dropped Objects



Animated moment – Work at Height – dropped object



Online quiz

INTERACTIVE RESOURCES


Access the Q3 interactive resource page [here](#)



Dropped Objects – Static & Dynamic



Dynamic Dropped Object Case Study



Dynamic Dropped Object Case Study



Toppled Crane – Doorbell Footage



All available resources and links can be accessed from the [Safe Lifting, Working at Height and Preventing Dropped Objects](#) page or accessed via the [Focal Point Resources](#) area.

If you are unable to access the restricted Focal Point Resources area, contact: nicola.taylor@stepchangeinsafety.net




Safety Alerts & Moments | 1 of 3

Safer Together: Operating Process Equipment - Loss of Containment

During routine operation on a Floating Production Storage and Offtake (FPSO) facility, a technician heard an unusual noise from the...


[Download here](#)



Safer Together: Maintaining Process Equipment - Loss of Containment

A plant was shut down due to a Tier 2 gas leak from a gas inlet header. Two throughwall defects were identified. Total loss over the...


[Download here](#)



Safer Together: Working On/Near Fixed Equipment - Person in Line of Fire

A polyurethane foam bumper end stop from a maintenance crane was found on the deck of an offshore facility. The bumper weighed about 5 kg...


[Download here](#)



Safer Together: Trailer detached from heavy vehicle during transit

A Heavy Vehicle was moving a rig over a distance of about 70km. On the return trip the Heavy Vehicle operator towed the dolly trailer by...

[Download here](#)



Safer Together: Driving collision with animal

Whilst travelling in the early morning a Toyota Landcruiser collided with a kangaroo. Upon impact the vehicle's steering was abruptly...


[Download here](#)



Safer Together: Operating Process Equipment - Loss of Containment

An inlet separator water boot level control valve failed to close at a Gas Processing Facility, causing both water and gas blow-by to the...

[Download here](#)






Safety Alerts & Moments | 2 of 3

IADC: A wedge shattered causing injury

Crew on a cargo vessel were preparing to open a cargo hold hatch cover, which was sealed by several wedges. The usual technique for...

[Download here](#)



IADC: Fast Rescue Boat (FRC) comes close to falling off in a dry dock

During an annual test of an FRC (Fast Rescue Craft) and davit on a vessel in dry dock, the boat tipped forward and collided with a railing...

[Download here](#)



IADC: Load lost from lorry on public road – inadequate securing of cargo

During the transportation of equipment, a load became free of its single retention strap and fell off a lorry onto a public road. The load...

[Download here](#)



IADC: Unsecured cargo inside box broke loose and fell

A load of cargo being lifted onto a vessel destabilised and the cargo, weighing over 400kg, fell approx. 5m from the load onto the vessel...


[Download here](#)



IADC: Side scuttle (porthole) knocked out by wave impact

While a platform supply vessel was on passage through heavy seas, a large wave hit the vessel and a side scuttle (porthole) in one of the...

[Download here](#)






Safety Alerts & Moments | 3 of 3

Dropped Wellhead Protection Structure During Decommissioning

When recovering a Subsea Xmas Tree, the load bearing capability of the wellhead connector was exceeded once the buoyancy effect of the...


[Download here](#)



July 2024 Master Link Failure

An offshore installation was undertaking supply boat operations and lifting containers up from the boat and onto the installation. After...

[Download here](#)



Search or submit your own learnings
via the [Alerts and Moments](#) page

