


These Moore & Wright gauges are ideally suited for measuring external grooves and other hard to reach outside dimensions.



Features

- For measuring external grooves and other hard to reach external dimensions
- Large LCD display
- Functions: mm/inch conversion, zero setting, tolerance setting, absolute or incremental modes, battery low indication
- Auto adjusting analogue display
- 0.005mm or 0.0002" resolution

Specification							
Code No	Range (mm)	Range (inch)	Accuracy (mm)	Dimn A (mm)	Dimn B (mm)	Dimn C (mm)	Contact Radius (mm)
MW442-01DC	0-10	0.2-0.4	±0.02	40.0	3.0	8.0	0.5
MW442-02DC	10-20	0.4-0.8	±0.02	40.0	3.0	8.0	0.5
MW442-03DC	20-30	0.8-1.2	±0.02	40.0	3.0	8.0	0.5
MW442-04DC	30-40	1.2-1.6	±0.02	40.0	3.0	8.0	0.5
MW442-05DC	40-50	1.6-2.0	±0.02	40.0	3.0	8.0	0.5