

Safety Flash

Crew transfer vessel (CTV) drifts onto turbine tower

Safety Flash Published on 20 February 2025 Generated on 3 April 2025 IMCA SF 03/25

A CTV drifted into and hit a nearby structure at 0.5 knots.

IOGP Life Saving Rules:



Work authorisation

What happened?

A crew transfer from a CTV to a Service Operation Vessel (SOV) was successfully completed. The SOV was 180 metres from a wind turbine generator (WTG) on the field. The CTV moved away from the SOV and propulsion controls were set to zero, and the crew continued to complete reporting and administrative tasks.

The CTV drifted into and hit the nearby structure at 0.5 knots, prompting the CTV Master to immediately move ahead and away to a safe area while vessel hull checks and reporting was carried out. The WTG asset was also inspected and some damage to the paintwork was noted. No-one was injured.

What went wrong?

- Administrative tasks were prioritised immediately after the crew transfer, rather than maintaining situational awareness.
- The instrumentation on the bridge of the CTV was not set up to warn of an imminent allision.
- Authority had been granted for the crew transfer to take place inside the WTG safety zone. The crew transfer should not have been authorised in this location.

Lessons learned

- The temptation to get administrative tasks out of the way should be resisted: Bridge crew should stay alert, maintain a good lookout and good situational awareness until a vessel is in a safe location after carrying out transfer operations.
 - Is there sufficient time to do these administrative tasks? Are CTV bridges appropriately crewed?
- Work Authorisation should consider vessel position in relation to fixed assets as well as wind / sea conditions.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with IMCA online. Sign-up to receive Safety Flashes straight to your email.