



Offshore platform decommissioning near miss

Fire on vessel - stray electrical current during welding

Vessel collision caused by mismatch between bridge and engine room control

Man overboard during motion compensated gangway transfer

Fall from height injury at container port

Tampering with approved safety devices

Injury to little finger

Laceration to right index finger

Fire in engine room

Smoke and fire on Main Engine Exhaust

Urgent inspection of pressurised carbon dioxide fire fighting systems

Safety pins left in fire suppression system – high potential near miss

Inappropriate automatic activation of fixed fire-fighting system



Loading & Unloading - Person Fall From Height

Lifting - Person in Line of Fire

Driving - Loss of Load



Vessel Stretcher Breakage



Damage to Wireline Unit During Supply Boat Operations

Poor Equipment Design & Human Error