

Posted at

16 h 28 m



FIA FIA WORLD TOURING CAR CUP

Doc No. 33

2020 FIA WTCR – RACE OF ARAGON

From The Stewards **Decision N° 6**
To The Competitor's Representative
Comtoy DHL Team Audi Sport

The Stewards, having received a report from the FIA Race Director (Report 4) and having reviewed video evidence, have considered the following matter, determine that a breach of the regulations has been committed by the Competitor named below and impose the penalty referred to.

Car No. 31 – T. Coronel
Competitor Comtoy DHL Team Audi Sport
Session After Free Practice 2
Time 14:23
Facts General safety incident – mechanic with fire extinguisher was not present during refuelling
Offence Committed a breach of Art. 35.10 b) of the 2020 FIA WTCR Sporting Regulations
Penalty **Fine of € 600** as per Art. 11.9 and Art. 12.1 of the FIA International Sporting Code

*The fine has to be paid to FIA within 48 hours.
Credit du Nord, 50, rue d'Anjou, F-75008 Paris
Code /BAN: FR76 3007 6020 2025 3680 0020 034. Swift Code: NORDFRPP*

Reason A mechanic with a fire extinguisher has to be present during refuelling.

The Competitor is reminded of his right to appeal in accordance with Article 15 of the FIA International Sporting Code.


Horst SEIDEL
FIA Steward (Chairman)


Yves BACQUELAÏNE
FIA Steward


Alejandro SORIANO
ASN Steward

Date 14 November 2020 **Time** 15:00

Received by the Competitor:
Comtoy DHL Team Audi Sport
Signature: Digital acknowledgement

Received and acknowledged via E-Mail:

Date: 14.11.2020
Time: 16:18

Copy to: The Competitor
The FIA Race Director
The Technical Delegate
The Press Delegate
The Timekeepers
The Official Notice Board