


Assembly diagram



TEXI QUATTRO 24 / TEXI CINQUE 35

Assembly can be carried by skilled workmen, mechanics who can assemble the machine themselves.

I. MACHINE HEAD BOX



+



+



+




chain, screwdrivers, box wrench,
Allen wrench, screws, rubbers,
washers, nuts, vaseline oil,
bent tweezers, silicone, funnel

thread stand

waste fabric chute, v-belt cover
LED lamp, plates, chute's holder,
soft cover

II. TEXI POWER 550 BOX



Texi Power 550 motor with speed controller, V-belt,
control box, screws, washers, nuts, V-belt cover,
lever pedal/motor

III. PREMIUM EX QUATRO 24 & CINQUE 35 BOX



TABLE TOP QC PREMIUM EX



+

TITANIUM Ti500




+

B-27 80s



+

STAND TEXI PREMIUM EX SILVER




+



A – 1x Drawer
B – 2x Slide
C – 4x S6
D – 6x S4
E – 4x WS6

+



A – 2x Grip
B – 4x M12
C – 12x M8
D – 3x M6
E – 4x WM12
F – 12x WM8
G – 3x WM6
H – 4x PM12
I – 12x NM8
J – 3x NM6
K – 4x 30106S

You will also need: 2x box wrench 10 mm, 2x box wrench 13 mm, box wrench 17 mm, box wrench 19 mm, driller, hammer, hose clamp.

1.



2.



4x M8, WM8, NM8

3.



4.



4x 30106S

5.



6.



4x M8, WM8, NM8

7.



8.



1x Grip, 2x M6, WM6, NM6

9.



10.



11.



2x M8, WM8, NM8

12.




13.



2x M12, WM12, PM12

14.



15.



16.



2x M12, WM12, PM12

17.



18.



1x Grip, 2x M6, WM6, NM6

19.



20.




2x M8, WM8, NM8

21.



22.



23.



24.



plate

25.



plate

1x Drawer
2x Slide
6x S4

26.




screw, washer, nut

27.



28.




29.




washer, nut

30.



rubber

31.



32.



33.




34.



rubber, washer, nut

35.




36.



Texi Power 550 motor


37.



38.




39.




40.



41.



42.




LED lamp

43.



44.




pull LED lamp's feeder cable through upper plate of control box


45.



46.




47.




pull out feeder cables (these with blue insulation)

48.




pull black and red wires of lamp's feeder cable through blue insulation

49.




solder wires onto tips of feeder cables

50.



put in feeder cables on their place


51.



52.



53.




54.




cable holders

55.



56.



4x S6, WS6

57.



lever pedal/motor

58.



59.




60.




rubbers

61.



62.



63.



V-belt

64.



V-belt cover

65.



66.



67.



68.



69.




leveling

70.



V-belt cover

71.



72.




73.



74.




75.




76.



77.



78.




79.




80.




81.



82.



83.



84.



LED lamp

85.




86.



87.



88.




89.



chain


90.




91.



93.



94.



95.



thread stand


96.



97.



98.



99.



100.




101.



102.



103.



waste fabric chute with holder

104.



105.




106.




107.



108.



109.



110.



111.





TEXI QUATTRO 24



TEXI CINQUE 35