











This picture shows the way in which the slings are crushed between units making it difficult for a forklift truck driver to assess if it is snagged or not.