



SAFETY MOMENTS & ALERTS

FEB – APR 14th 2025



LTI – Hairline Fracture to Wrist During Scaffolding Operations

Dropped Object from Crane Boom Tip Causing Injury to IP Foot



Snagged Lift

Potential Dropped Object

Spill During Bulk Transfer

Safe Boarding Arrangements for Marine Pilots



Risk of collision with offshore installations from attendant vessels

[click here to Submit an Alert](#)

[click here for Alerts & Moments Page](#)





MAIB: Step-ladder failure (LTI)

MAIB: Vessel cook injured by spillage of burning cooking oil

Confined space entry hot work fatality

MAIB: Parted mooring rope leads to fatality

Saturation diver exposed to chemicals from pipeline

A broken stretcher could have led to injury

Positive story: Excellent galley hygiene and housekeeping

Fauna Entanglement

Cook got chemicals in eye

Crew transfer vessel (CTV) drifts onto turbine tower

LTI: Fall from height during FRC maintenance

Near miss: narrowly avoided fall from height due to missing deck gratings

Injuries during lifting operations

LTI: rope under tension moved and hit person's hand

Divers helmet struck and damaged subsea by crane hook



Diver lifted off seabed

Very serious leg injury during crane operations

Person fell in engine room and injured head

Finger injury during manual handling

Acetylene gas explosion

Crane cab fire caused by fridge

Incidents occurring during decommissioning



Water Storage Reservoir Fatality



Operating Process Equipment - Fire