



Main Crane failure during load test

AC vent unit cover dislodged and fell 1.7m

Dropped sheave and clump weight

Incident during rig decommissioning leads to fatality

Successful rescue of surfer on the open sea

Diver exposed to unplanned release of production gas

Dropped Object - Wooden Packing Block

Person Fell Through Open Hatch

Fire on vessel – escaped exhaust gases

Snagging hazards

Finger injury during emergency recovery of ROV

Recurring hand injuries from alternative cutting devices

Hot work performed outside of Permit to Work (PTW) boundary limit

Vital safety information (height of vehicle) found incorrect

Crane wire failure



Working with Chemicals - Explosion

Working with Electrical Equipment - Fire



Chemical Contact with Cooks Eye

Burns from Pot Handling in Galley



Stop Use and Action Notification - Select 3M™ DBI-SALA® Sealed-Blok™ Self-Retracting Lifelines



LTI - Eye Injury

Dropped Handrail Fell 6m to Walkway Below

Safety Moment Pack: Occupational Lung Disease & Respiratory Protective Equipment (RPE)